Declassified in Part - Sanitized Copy Approved for Re	elease 2012/01/05 : CIA-RDP82-00457R0	04600640014-0
	A TACOFFROLOG COP	Harter Alban
COUNTRY Seviet Zone of Germany		rescribencia
TG. C Werneuchen Airfield	dda a'r a dd 18 a'r y ynglegg wyg y sife hiddig a'r llwysdi awlad di addig dan gwannau addig addig yn gall y d All a a'r a dd 18 a'r y ynglegg wyg y sife hiddig a'r llwysdi awlad addig dan gall addig ar gall ar gall a ddig	19-4. Section (18)
Machine a Marie Machine and a gray was		50X1-HUM
EVALUATION		- 4 mm доминости стат стату при съдосно посто до стато посторо стато посто посто посто посто стато стато стато В посто посто стато с
DATE OF CONTENT.	W. All Richards 1988A. No gainst industrial materials are supported by the control of the contro	. And garding december (Assessed Section 1) and the sec of the section of the sec
DATE OBTAINED		1
REFERENCES		
PAGES 2 ENCLOSURES (NO. & TYPE) REMARKS		50X1-HUM
		50X1-HUM
taken on trucks	50 Soviet Air Force officers' and household utensils. were	50X1-HUM 50X1-HUM
twin-engine planes pract planes with two hunch-sh rear one being higher. m	aircraft covered with in front of the closed 19 January 1950. Six more ciced flying. Three of the maped cabin canopies, the made local flights but the through cabin roofs made	

- tarpaulins were counted in front of the closed hangars of the field on 19 January 1950. Six more twin-engine planes practiced flying. Three of the planes with two hunch-shaped cabin canopies, the rear one being higher, made local flights but the other three planes with through cabin roofs made long distance flights. It was observed that one plane proceeded southwest, returned from the same direction 20 to 30 minutes later, flew over the field, then headed northeast and returned from that direction about 20 minutes later. Guide beam approach flights were probably practiced at the field.
- Description of twin-engine low-wing monoplanes:
 Double rudder assembly, in-line engine, landing
 gear retracting rearward into engine cowling. Two
 slots for armaments recognized at underside of
 metal-covered nose. Antenna rod at front section
 of cockpit roof. Elevator assembly in slight
 dihedral, wings tapering. Hunch-shaped or through
 cabin roofs. Planes with through cabin roofs had
 dive brake set under wings bet een engine and wing
 tips. A ventral flap with glazed slot, probably
 for armaments, at bottom side of fuselage in line
 with trailing edge of wings.

CLASSIFICATION SECRET/CONTROL US OFF CTASE

This document is hereby regraded to CONFIG. At in accordance with the letter of the Configuration of the Director of the contain intelligence to the

50X1-HUM

Archivist of the United States.

CONFIDENTIAL

CONTROL/US OFFICIALS ONLY

50X1-HUM

This description applies only to the operated planes which were operated on 19 January.

- Two tank trucks, a fire truck, an ambulance, a truck and passenger car were standing at the take-off point. Flying did not stop at noon. A truck went twice between the take-off point and the billets to exchange the flying crews. The take-off direction was marked by red and white flags. A landing cross was laid. The operated planes had white propeller hubs and figures. The landings were well performed.
- A radio truck with an antenna rod, from 8 to 10 meters high, was in the southwest section of the field. The radio station east of the field was occupied by an officer and three EM, but only during flying. The Werneuchen-East telephone exchange was occuried. Twelve young air force soldiers were drilling there.
- 6. Firing with carbines and machine guns was practiced on the east edge of the field throughout th day. The railroad spur track at the field was rusty. The dependents' billets were still fully occuried by Soviet Air Force families. There was strikingly little motor vehicle traffic toward the field. ____ motor vehicle shuttled between the field and the town. Supply truck entered the field.

50X1-HUM

50X1-HUM

50X1-HUM

Comment:

50X1-HUM

a. The transfer of Soviet dependents was reported from several places in the Soviet Zone of Germany. Married officers are apparently exchanged for unmarried officers.

b. The type and number of aircraft observed at the field confirm the previously assumed occupation by component units of the III Bmr Corps. Two regiments are ca ried in Werneuchen. The model designation and the tactical employment of the two twin-engine aircraft types has not been determined. The observation that the planes have no plexiglass noses leads to the assumption that they are PE-3s. The slots on the underside of the nose are rossibly for the fitting of armament.

AT/CONTROL/US OFFICIALS OF X